



Note to Erector:-
 Holes connecting main beam at lower
 end of diagonal in East Column at all bents
 to be reamed in field for adjustment.
 Before setting 1551 and 1552 notify
 customer and allow them opportunity to see
 2 or 3 heavy cuts of paint on account of necessary
 after erection

WISCONSIN BRIDGE & IRON CO.
 NORTH MILWAUKEE, WISCONSIN

CONTRACT NO. 9199
 ERRECTED BY W.B.I.C.
 FOR Dept. of Public Works, City of Detroit.
 LOCATION Vermont Street on McE.R. Detroit.

DESCRIPTION Highway Viaduct.
 DETAILS OF Erection Diagram REAMING

INSPECTION BY
 SHOP PAINT
 FIELD PAINT

RIVETS
 MADE BY
 TRACED BY
 CHECKED BY

OPEN HOLES
 DATE 12-5-10
 HAVE

EXCEPT AS NOTED
 DATE 12-5-10
 DATE

SCALE SECTION
 DATE REVISED
 SHEET NO. 12
 9199