



CONSTRUCTION CONSULTING & TESTING, INC.

TOLEDO OFFICE - 430 Bishop Rd. Ste A Bowling Green, Ohio 43402 Ph.: (419) 878-7304

DETROIT OFFICE - 35410 Mound Rd. Sterling Hts., Michigan 48310 Ph.: (586) 795-2877

Client: Century Cement
12670 Sibley Road
Riverview, MI 48193

Project: Conner
Wayne Co.:

Date: June 18, 2022

CCT No.: 201-22037-1A

REPORT OF CONCRETE COMPRESSIVE STRENGTH

DATE OF POUR: 5/21/2022

LOCATION OF POUR: Sidewalk: NB Conner & Jefferson

SUPPLIER: Hercules

TICKET NO.: 438998
MIX I.D.: P1-DETM

FIELD DATA: Set 1 of 1

DATE: 5/21/2022
BATCH TIME: 7:05 AM
TEST TIME: 8:30 AM
AIR CONTENT (%): 5.7%
SLUMP (in.): 5 1/2
CONC. TEMP. (F): 46
AIR TEMP. (F): 72
UNIT WT. (pcf): ---
MOLDED BY: CCT

***Testing conforms to ASTM C 172, C 231, C 143, C 1064, C 138, C 31, & C 39/C 39M

LAB NO.	BREAK DATE	AGE (days)	DIA. (in)	AREA (sq. in.)	LOAD (lbs)	COMPRESSIVE STRENGTH (psi)	TYPE OF FRACTURE
397	06/18/22	28	4	12.56	51,330	4090	5
398	06/18/22	28	4	12.56	48,690	3880	5

Cylinder Size: 4" x 8"

28 DAY AVERAGE

3,985

28 DAY SPEC.


3,500

Comments:


Reviewed By:

Mitch Forst, President

Distribution: Century Cement



Type 1
Reasonably well-formed cones on both ends, less than 1 in. [25 mm] of cracking through caps




Type 2
Well-formed cone on one end, vertical cracks running through both ends, no well-defined cone on other end



Type 3
Columnar vertical cracking through both ends, no well-formed cones



Type 4
Diagonal fracture with no cracking through ends; tap with hammer to distinguish from Type 1



Type 5
Side fractures at top or bottom (occur commonly with unbonded caps)



Type 6
Similar to Type 5 but end of cylinder is pointed

Typical Fracture Patterns