

INSPECTOR'S REPORT OF CONCRETE PLACED - Roadway

FILE 210

CONTRACTOR <u>Merlo Construction</u>		GENERAL NAME OF PROJECT <u>MDOT-Various Detroit</u>	
SUBCONTRACTOR		CONTROL SECTION ID - JOB NUMBER	
CONCRETE SUPPLIER <u>Superior Materials</u>		ROUTE <u>Spinoza Dr</u>	
MAXIMUM TIME <u>90 minutes</u>		STRUCTURE NUMBER	
WEATHER <u>Partly cloudy</u> A.M. _____ P.M. _____		REPORT NUMBER	
MAX. WATER ADDED PER CYD GALLONS		DATE <u>6/5/20</u>	
REASON:			

BEAMS/CYLINDERS MADE (Sta, Time, #, etc.) ① North Side Curb of Spinoza Dr North of Joy Rd CURING COMPND. USED GALLONS

Intended Air 5.5 % to 8.5 % TEMPERATURES - AIR - SLUMP Intended Slump 0 " to 3 "

TIME	ATMOSPHERE	CONCRETE	*AIR CONTENT %	SLUMP	CYLINDERS/ BEAMS	TIME	ATMOSPHERE	CONCRETE	*AIR CONTENTS %	SLUMP	CYLINDERS/ BEAMS
10:40am	82°F	81°F	5.7%	2.5"	4						

LOT #	LOT SIZE	SUBLOT #	SUBLOT SIZE	RANDOM #	QA Cylinder ID	Discrepancy Cylinder

COMMENTS *paired by truck chute

ITEM OR CODE NO.	STA. TO STA.	GRADE OF CONC.	LENGTH	WIDTH	DEPTH	MEASURED SQ. OR CU. YARDS	CYDS. PLAN	CYDS. USED	CYDS. WASTE	OVER UNDER %

REMARKS OR COMPUTATIONS
(Use back if necessary)

① ticket 2497944
P155E7CQA032

MIX OR STREET TECHNICIAN

Mallory Grager

DATE 6/5/20

