

INSPECTOR'S REPORT OF CONCRETE PLACED - Roadway

FILE 210

CONTRACTOR Merlo construction		GENERAL NAME OF PROJECT MDOT-Various Detroit	
SUBCONTRACTOR		CONTROL SECTION ID - JOB NUMBER	
CONCRETE SUPPLIER Superior Materials		ROUTE McClellan Ave	
MAXIMUM TIME 90 minutes		STRUCTURE NUMBER	
WEATHER mostly sunny A.M. mostly sunny P.M.		REPORT NUMBER	DATE 6/1/20
MAX. WATER ADDED PER CYD GALLONS	REASON:		
BEAMS/CYLINDERS MADE (Sta, Time, #, etc.)		CURING COMPND. USED GALLONS	
① SE corner curb McClellan & Emmons		② SE ADA sidewalk McClellan & Cutler	
Intended Air 5.5 % to 8.5 %		TEMPERATURES - AIR - SLUMP Intended Slump 0 " to 3/6 "	

TIME	ATMOSPHERE	CONCRETE	*AIR CONTENT %	SLUMP	CYLINDERS/ BEAMS	TIME	ATMOSPHERE	CONCRETE	*AIR CONTENTS %	SLUMP	CYLINDERS/ BEAMS
① 8:00 am	65°F	69°F	5.8%	15"	4						
② 11:50 am	68°F	78°F	6.2%	4"	4						

LOT #	LOT SIZE	SUBLOT #	SUBLOT SIZE	RANDOM #	QA Cylinder ID	Discrepancy Cylinder

COMMENTS **poured by truck chute**

ITEM OR CODE NO.	STA. TO STA.	GRADE OF CONC.	LENGTH	WIDTH	DEPTH	MEASURED SQ. OR CU. YARDS	CYDS. PLAN	CYDS. USED	CYDS. WASTE	OVER UNDER %

REMARKS OR COMPUTATIONS
(Use back if necessary) **① ticket 2495785** **② ticket 2495963**
P155ETCQA032 **P155ERCQA032**

MIX OR STREET TECHNICIAN **Mallory Grager** **Mary Grager** DATE **6/1/20**

