

INSPECTOR'S REPORT OF CONCRETE PLACED - Roadway

FILE 210

CONTRACTOR <u>Merlo Construction</u>		GENERAL NAME OF PROJECT <u>MDOT-Various Detroit</u>	
SUBCONTRACTOR		CONTROL SECTION ID - JOB NUMBER	
CONCRETE SUPPLIER <u>Superior Materials</u>		ROUTE <u>McClellan Ave</u>	
MAXIMUM TIME <u>90 minutes</u>		STRUCTURE NUMBER	
WEATHER <u>partly cloudy</u> A.M. <u>mostly sunny</u> P.M.		REPORT NUMBER	DATE <u>6/2/20</u>
MAX. WATER ADDED PER CYD GALLONS	REASON:		
BEAMS/CYLINDERS MADE (Sta, Time, #, etc.)		CURING COMPND. USED	

McClellan + Agnes						McClellan + Agnes						GALLONS	
Intended Air <u>5.5</u> % to <u>8.5</u> %			TEMPERATURES - AIR - SLUMP			Intended Slump <u>0</u> " to <u>3/6</u> "							
TIME	ATMOSPHERE	CONCRETE	*AIR CONTENT %	SLUMP	CYLINDERS BEAMS	TIME	ATMOSPHERE	CONCRETE	*AIR CONTENTS %	SLUMP	CYLINDERS BEAMS		
4:45 am	70°F	79°F	5.8%	2"	4	5:40 pm	70°F	85°F	5.5%	4.5"	4		
								85°F	5.5%	4.5"	4		
2:20 pm	81°F	81°F	6.0%	5"	4								
3:35 pm	84°F	83°F	6.2%	5"	—								

LOT #	LOT SIZE	SUBLOT #	SUBLOT SIZE	RANDOM #	QA Cylinder ID	Discrepancy Cylinder

COMMENTS *poured by truck chute

ITEM OR CODE NO.	STA. TO STA.	GRADE OF CONC.	LENGTH	WIDTH	DEPTH	MEASURED SQ. OR CU. YARDS	CYDS. PLAN	CYDS. USED	CYDS. WASTE	OVER UNDER %

REMARKS OR COMPUTATIONS (Use back if necessary) ① ticket 2496310 ② ticket 2496428 ③ ticket 2496537
P155ETCQA032 P155ETCQA032 P155ETCQA032
④ ticket 2496643 P155ETCQA032

MIX OR STREET TECHNICIAN Mallory Grager Mary Grager DATE 6/2/20

