

INSPECTOR'S REPORT OF CONCRETE PLACED - Roadway

FILE 210

CONTRACTOR Merio Construction		GENERAL NAME OF PROJECT MDOT-Various Detroit	
SUBCONTRACTOR		CONTROL SECTION ID - JOB NUMBER	
CONCRETE SUPPLIER Superior Materials		ROUTE McClellan Ave	
MAXIMUM TIME 90 minutes		STRUCTURE NUMBER	
WEATHER partly cloudy A.M. _____ P.M. _____		REPORT NUMBER	DATE 6/3/20

MAX. WATER ADDED PER CYD GALLONS	REASON:	BEAMS/CYLINDERS MADE (Sta, Time, #, etc.) ① SE corner curb at McClellan+Dorchester ② NE ADA sidewalk at McClellan+Agnes		CURING COMPND. USED GALLONS
-------------------------------------	---------	---	--	--------------------------------

Intended Air <u>5.5 %</u> to <u>8.5 %</u>			TEMPERATURES – AIR – SLUMP						Intended Slump <u>0 "</u> to <u>3/6 "</u>		
TIME	ATMOSPHERE	CONCRETE	*AIR CONTENT %	SLUMP	CYLINDERS/ BEAMS	TIME	ATMOSPHERE	CONCRETE	*AIR CONTENTS %	SLUMP	CYLINDERS/ BEAMS
:15am	77°F	80°F	5.5%	2.5"	4						
:05pm	81°F	82°F	6.2%	5.5"	4						

LOT #	LOT SIZE	SUBLOT #	SUBLOT SIZE	RANDOM #	QA Cylinder ID	Discrepancy Cylinder

COMMENTS ***poured by truck chute**

ITEM OR CODE NO.	STA. TO STA.	GRADE OF CONC.	LENGTH	WIDTH	DEPTH	MEASURED SQ. OR CU. YARDS	CYDS. PLAN	CYDS. USED	CYDS. WASTE	OVER UNDER %

REMARKS OR COMPUTATIONS (Use back if necessary)
① ticket 2496864 PISSEB CQA032 ② ticket 2496864 PISSEB CQA032

MIX OR STREET TECHNICIAN Mallory Grager Mary Grogg	DATE 6/3/20
--	-----------------------

