

INSPECTOR'S REPORT OF CONCRETE PLACED - Roadway

FILE 210

CONTRACTOR Merlo Construction		GENERAL NAME OF PROJECT MDOT-Various Detroit	
SUBCONTRACTOR		CONTROL SECTION ID - JOB NUMBER	
CONCRETE SUPPLIER Superior Materials		ROUTE McClellan Ave	
MAXIMUM TIME 90 minutes		STRUCTURE NUMBER	
WEATHER clear A.M. partly cloudy P.M.		REPORT NUMBER	DATE 6/4/20
MAX. WATER ADDED PER CYD GALLONS		REASON:	

BEAMS/CYLINDERS MADE (Sta, Time, #, etc.) **① NE corner curb McClellan+Canfield** **② SE corner ADA sidewalk McClellan+Garten**

Intended Air **55 % to 8.5 %** TEMPERATURES - AIR - SLUMP Intended Slump **0 " to 3/6 "**

TIME	ATMOSPHERE	CONCRETE	*AIR CONTENT %	SLUMP	CYLINDERS/ BEAMS	TIME	ATMOSPHERE	CONCRETE	*AIR CONTENTS %	SLUMP	CYLINDERS/ BEAMS
① 9:15am	73°F	77°F	6.4%	2.5"	4						
② 1:20pm	81°F	82°F	5.6%	4.5"	4						

LOT #	LOT SIZE	SUBLOT #	SUBLOT SIZE	RANDOM #	QA Cylinder ID	Discrepancy Cylinder

COMMENTS ***poured by truck chute**

ITEM OR CODE NO.	STA. TO STA.	GRADE OF CONC.	LENGTH	WIDTH	DEPTH	MEASURED SQ. OR CU. YARDS	CYDS. PLAN	CYDS. USED	CYDS. WASTE	OVER UNDER %

REMARKS OR COMPUTATIONS (Use back if necessary) **① ticket 2497336 PI55E7CQA032** **② ticket 2497652 PI55E7CQA032**

MIX OR STREET TECHNICIAN **Mallory Grager** *Mary Grager* DATE **6/4/20**

