

INSPECTOR'S REPORT OF CONCRETE PLACED - Roadway

FILE 210

CONTRACTOR Merio Construction		GENERAL NAME OF PROJECT MDOT-Various Detroit	
SUBCONTRACTOR		CONTROL SECTION ID - JOB NUMBER	
CONCRETE SUPPLIER Superior Materials		ROUTE McClellan Ave	
MAXIMUM TIME 90 minutes		STRUCTURE NUMBER	
WEATHER Partly cloudy A.M. _____ P.M. _____		REPORT NUMBER	DATE 6/5/20

MAX. WATER ADDED PER CYD GALLONS	REASON:	CURING COMPND. USED GALLONS
BEAMS/CYLINDERS MADE (Sta, Time, #, etc.) ① ONE corner ADA ramp/sidewalk at McClellan & Barry St		
Intended Air 5.5 % to 8.5 %		TEMPERATURES - AIR - SLUMP Intended Slump 0 " to 6 "

TIME	ATMOSPHERE	CONCRETE	*AIR CONTENT %	SLUMP	CYLINDERS/ BEAMS	TIME	ATMOSPHERE	CONCRETE	*AIR CONTENTS %	SLUMP	CYLINDERS/ BEAMS
① 9:10am	79°F	78°F	5.5%	6"	4						

LOT #	LOT SIZE	SUBLOT #	SUBLOT SIZE	RANDOM #	QA Cylinder ID	Discrepancy Cylinder

COMMENTS ***poured by truck chute**

ITEM OR CODE NO.	STA. TO STA.	GRADE OF CONC.	LENGTH	WIDTH	DEPTH	MEASURED SQ. OR CU. YARDS	CYDS. PLAN	CYDS. USED	CYDS. WASTE	OVER UNDER %

REMARKS OR COMPUTATIONS
(Use back if necessary) **① ticket 2497870
PISSERCQA032**

MIX OR STREET TECHNICIAN Mallory Grager	DATE 6/5/20
---	-----------------------

