

INSPECTOR'S REPORT OF CONCRETE PLACED - Roadway

FILE 210

CONTRACTOR Merlo Construction		GENERAL NAME OF PROJECT MDOT-Various Detroit	
SUBCONTRACTOR		CONTROL SECTION ID - JOB NUMBER	
CONCRETE SUPPLIER Superior Materials		ROUTE McClellan Ave	
MAXIMUM TIME 90 minutes		STRUCTURE NUMBER	
WEATHER Mostly Sunny A.M. Mostly Sunny P.M.		REPORT NUMBER	DATE 6/9/20

MAX. WATER ADDED PER CYD GALLONS	REASON:	BEAMS/CYLINDERS MADE (Sta, Time, #, etc.) ① curb E side McClellan S of Laura ② NE corner ADA ramps/sidewalk at McClellan & Cross St	
Intended Air 5.5 % to 8.5 %		TEMPERATURES - AIR - SLUMP	Intended Slump 0 " to 3/6 "

TIME	ATMOSPHERE	CONCRETE	*AIR CONTENT %	SLUMP	CYLINDERS/BEAMS	TIME	ATMOSPHERE	CONCRETE	*AIR CONTENTS %	SLUMP	CYLINDERS/BEAMS
① 8:14am	68°F	82°F	6.6%	4.5"	4						
② 1:22pm	89°F	87°F	7.2%	5"	4						

LOT #	LOT SIZE	SUBLOT #	SUBLOT SIZE	RANDOM #	QA Cylinder ID	Discrepancy Cylinder

COMMENTS ***truck chute**

ITEM OR CODE NO.	STA. TO STA.	GRADE OF CONC.	LENGTH	WIDTH	DEPTH	MEASURED SQ. OR CU. YARDS	CYDS. PLAN	CYDS. USED	CYDS. WASTE	OVER UNDER %

REMARKS OR COMPUTATIONS (Use back if necessary) **① ticket 2499034 HE7E8CQA032** **② ticket 2499289 HE7E8CQA032**

MIX OR STREET TECHNICIAN **Mallory Grager** **Mary Gray** DATE **6/9/20**

