

INSPECTOR'S REPORT OF CONCRETE PLACED - Roadway

FILE 210

CONTRACTOR Merlo Construction		GENERAL NAME OF PROJECT MDOT-Various Detroit	
SUBCONTRACTOR		CONTROL SECTION ID - JOB NUMBER	
CONCRETE SUPPLIER Superior Materials		ROUTE McClellan Ave	
MAXIMUM TIME 90 minutes		STRUCTURE NUMBER	
WEATHER mostly cloudy A.M. partly cloudy P.M.		REPORT NUMBER	DATE 6/10/20
MAX. WATER ADDED PER CYD GALLONS	REASON:		

BEAMS/CYLINDERS MADE (Sta, Time, #, etc.)

① SE corner ADA ramps / ② NE corner ADA ramps / ③ Sidewalk at 4539 McClellan
Sidewalk McClellan + Barker + Chapin

Intended Air **5.5 % to 8.5 %**

TEMPERATURES - AIR - SLUMP

Intended Slump **0 "** to **6 "**

TIME	ATMOSPHERE	CONCRETE	*AIR CONTENT %	SLUMP	CYLINDERS BEAMS	TIME	ATMOSPHERE	CONCRETE	*AIR CONTENTS %	SLUMP	CYLINDERS/ BEAMS
① 8:10am	79°F	84°F	5.8%	5"	4						
② 9:30am	81°F	84°F	6.4%	4.5"	4						
③ 3:20pm	88°F	90°F	5.5%	4"	4						

LOT #	LOT SIZE	SUBLOT #	SUBLOT SIZE	RANDOM #	QA Cylinder ID	Discrepancy Cylinder

COMMENTS ***poured by truck chute**

ITEM OR CODE NO.	STA. TO STA.	GRADE OF CONC.	LENGTH	WIDTH	DEPTH	MEASURED SQ. OR CU. YARDS	CYDS. PLAN	CYDS. USED	CYDS. WASTE	OVER UNDER %

REMARKS OR COMPUTATIONS
(Use back if necessary)

① Ticket 249942 SH5ERCQA032 ② Ticket 2499549 P155ERCQA032 ③ Ticket 2499766 P155ERCQA032

MIX OR STREET TECHNICIAN

Mallory Grager

DATE

6/10/20

eti