

INSPECTOR'S REPORT OF CONCRETE PLACED - Structure

FILE 206

MDOT-VARIOUS DETROIT

CONTRACTOR MERLL CONSTRUCTION

GENERAL NAME OF PROJECT LAFAYETTE + VERNOR

SUBCONTRACTOR

CONTROL SECTION ID - JOB NUMBER

CONCRETE SUPPLIER SUPERIOR MATERIALS

ROUTE

MAXIMUM TIME 90 MINUTES

STRUCTURE NUMBER

WEATHER SUNNY A.M. SUNNY P.M.

REPORT NUMBER

DATE 6.30.20

MAX. WATER ADDED PER CYD GALLONS

REASON

0125

BEAMS/CYLINDERS MADE (Sta, Time, #, etc.)

CURING COMPND. USED GALLONS

Intended Air 5.5 % to 8.5 %

TEMPERATURES - AIR - SLUMP Intended Slump 0 " to 5 "

TIME	ATMOSPHERE	CONCRETE	AIR CONTENT %	SLUMP	CYLINDERS/ BEAMS	TIME	ATMOSPHERE	CONCRETE	AIR CONTENTS %	SLUMP	CYLINDERS/ BEAMS
① 7:10	65	83	7.0	3.5	4						
② 11:10	79	86	7.1	3.5	4						

LOT #	LOT SIZE	SUBLOT #	SUBLOT SIZE	RANDOM #	Q.A. Cylinder ID	SAMPLE ID	Discrepancy ID

COMMENTS -SAMPLE FROM TRUCK CHUTE

STRUCTURE ITEMS PLACED

DESCRIPTION OF POUR	GRADE OF CONCRETE
PLAN VOLUME OF POUR	AGGREGATE CORRECTION FACTOR
ACTUAL QUANTITY PLACED	EVAPORATION RATE
DIFFERENCE	WASTE OR REJECTED
REMARKS OR COMPUTATIONS (Use back if necessary)	TIME OF POUR From _____ To _____

MIX OR STREET TECHNICIAN

Biguzman / Notary

DATE 6.30.20

① TICKET - 2506201
PISSERCNA002

② TICKET - 2506377
PISSERCNA002

S/SIDEWALK
LAFAYETTE + HELEN ST

N. SIDEWALK
ON VERNOR + McDOWGALL

