

INSPECTOR'S REPORT OF CONCRETE PLACED - Roadway

FILE 210

CONTRACTOR <u>Merlo Construction</u>		GENERAL NAME OF PROJECT <u>MDOT-VariouS Detroit</u>	
SUBCONTRACTOR		CONTROL SECTION ID - JOB NUMBER	
CONCRETE SUPPLIER <u>Superior Materials</u>		ROUTE <u>SB M-39 Service Drive</u>	
MAXIMUM TIME		STRUCTURE NUMBER	
WEATHER <u>clear</u> A.M. <u>clear</u> P.M.		REPORT NUMBER	DATE <u>7/8/20</u>

MAX. WATER ADDED PER CYD GALLONS	REASON:	CURING COMPND. USED GALLONS
BEAMS/CYLINDERS MADE (Sta, Time, #, etc.) <u>① curb NW corner of SB M-39 SD & Van Buren</u> <u>② ADA ramps/sidewalk NW corner of SB M-39 SD & Van Buren</u>		
Intended Air <u>5.5</u> % to <u>8.5</u> %	TEMPERATURES - AIR - SLUMP	Intended Slump <u>0</u> " to <u>3/6</u> "

TIME	ATMOSPHERE	CONCRETE	*AIR CONTENT %	SLUMP	CYLINDERS/ BEAMS	TIME	ATMOSPHERE	CONCRETE	*AIR CONTENTS %	SLUMP	CYLINDERS/ BEAMS
① 9:05am	81°F	87°F	5.7%	2"	4						
② 12:05pm	88°F	89°F	5.7%	4"	4						

LOT #	LOT SIZE	SUBLOT #	SUBLOT SIZE	RANDOM #	QA Cylinder ID	Discrepancy Cylinder

COMMENTS Spoured by truck chute

ITEM OR CODE NO.	STA. TO STA.	GRADE OF CONC.	LENGTH	WIDTH	DEPTH	MEASURED SQ. OR CU. YARDS	CYDS. PLAN	CYDS. USED	CYDS. WASTE	OVER UNDER %

REMARKS OR COMPUTATIONS (Use back if necessary)	① ticket 2508634 P155E7CQA032 10cyd	② ticket 2508771 P155SERCQA032	DATE <u>7/8/20</u>
MIX OR STREET TECHNICIAN	<u>Mallory Grager</u>		

