

INSPECTOR'S REPORT OF CONCRETE PLACED - Roadway

FILE 210

CONTRACTOR <u>Memo Construction</u>		GENERAL NAME OF PROJECT <u>MDOT-Various Detroit</u>	
SUBCONTRACTOR		CONTROL SECTION ID - JOB NUMBER	
CONCRETE SUPPLIER <u>Superior Materials</u>		ROUTE <u>Woodmere St</u>	
MAXIMUM TIME		STRUCTURE NUMBER	
WEATHER <u>partly cloudy A.M. partly cloudy P.M.</u>		REPORT NUMBER	DATE <u>7/21/20</u>

MAX. WATER ADDED PER CYD GALLONS	REASON:	BEAMS/CYLINDERS MADE (Sta, Time, #, etc) <u>3 W side ADA ramps/sidewalk on Woodmere St at Wendell St</u>	CURING COMPND. USED GALLONS
-------------------------------------	---------	--	--------------------------------

Intended Air 5.5 % to 8.5 % TEMPERATURES - AIR - SLUMP Intended Slump 0 " to 6 "

TIME	ATMOSPHERE	CONCRETE	*AIR CONTENT %	SLUMP	CYLINDERS/ BEAMS	TIME	ATMOSPHERE	CONCRETE	*AIR CONTENTS %	SLUMP	CYLINDERS/ BEAMS
8:10am	69°F	86°F	7.7%	6.25"	—						
9:30am	70°F	84°F	5.2/5.5%	6"	—						
10:50am	70°F	84°F	5.8%	5"	4						

LOT #	LOT SIZE	SUBLOT #	SUBLOT SIZE	RANDOM #	QA Cylinder ID	Discrepancy Cylinder

COMMENTS *poured by truck chute

ITEM OR CODE NO.	STA. TO STA.	GRADE OF CONC.	LENGTH	WIDTH	DEPTH	MEASURED SQ. OR CU. YARDS	CYDS. PLAN	CYDS. USED	CYDS. WASTE	OVER UNDER %

REMARKS OR COMPUTATIONS (Use back if necessary) ① ticket 2512876 / ② ticket 2512940 / ③ ticket 2513003
P155E7CQA032 / P155ERCNA002 / P155ERCNA002

MIX OR STREET TECHNICIAN Mallory Grager Mallory Grager (LOAD REJECTED) 5.2% air retested to 5.5% (LOAD REJECTED)
DATE 7/21/20

