

INSPECTOR'S REPORT OF CONCRETE PLACED - Roadway

FILE 210

CONTRACTOR Merio Construction		GENERAL NAME OF PROJECT MDOT-Various Detroit	
SUBCONTRACTOR		CONTROL SECTION ID - JOB NUMBER	
CONCRETE SUPPLIER Superior Materials		ROUTE Joseph Campau St & E Vernor Hwy	
MAXIMUM TIME 90 minutes		STRUCTURE NUMBER	
WEATHER partly cloudy A.M. partly cloudy P.M.		REPORT NUMBER	DATE 7/23/20

MAX. WATER ADDED PER CYD GALLONS	REASON:	BEAMS/CYLINDERS MADE (Sta, Time, #, etc.) ① SE corner ADA ramps at Joseph Campau & Grant ② SE ADA curb at Vernor & Dubois	CURING COMPND. USED GALLONS
-------------------------------------	---------	---	--------------------------------

Intended Air **5.5 %** to **8.5 %** TEMPERATURES - AIR - SLUMP Intended Slump **0 "** to **6/3 "**

TIME	ATMOSPHERE	CONCRETE	*AIR CONTENT %	SLUMP	CYLINDERS/ BEAMS	TIME	ATMOSPHERE	CONCRETE	*AIR CONTENTS %	SLUMP	CYLINDERS/ BEAMS
① 9:30am	74°F	82°F	5.7%	4.5"	4						
② 11:45am	78°F	89°F	6.8%	2"	4						

LOT #	LOT SIZE	SUBLOT #	SUBLOT SIZE	RANDOM #	QA Cylinder ID	Discrepancy Cylinder

COMMENTS ***poured by truck chute**

ITEM OR CODE NO.	STA. TO STA.	GRADE OF CONC.	LENGTH	WIDTH	DEPTH	MEASURED SQ. OR CU. YARDS	CYDS. PLAN	CYDS. USED	CYDS. WASTE	OVER UNDER %

REMARKS OR COMPUTATIONS (Use back if necessary)
① ticket 2513894 PI55ER1QA032 19 cyd
② ticket PI55E71QA032 8 cyd

MIX OR STREET TECHNICIAN
Mallory Grager **Manny Gung** DATE **7/23/20**

