

INSPECTOR'S REPORT OF CONCRETE PLACED - Roadway

FILE 210

CONTRACTOR <u>Merlo Construction</u>		GENERAL NAME OF PROJECT <u>MDOT-Various Detroit</u>	
SUBCONTRACTOR		CONTROL SECTION ID - JOB NUMBER	
CONCRETE SUPPLIER <u>Superior Materials</u>		ROUTE <u>E Vernor Hwy</u>	
MAXIMUM TIME <u>90 minutes</u>		STRUCTURE NUMBER	
WEATHER <u>clear</u> A.M. P.M.		REPORT NUMBER	DATE <u>7/24/20</u>

MAX. WATER ADDED PER CYD GALLONS	REASON:
<u>ONE corner curb at (2) NE corner ADA ramps/sidewalk Vernor and Joseph Campus at Vernor & Dubois</u>	
BEAMS/CYLINDERS MADE (Sta, Time, #, etc)	CURING COMPND. USED GALLONS
Intended Air <u>5.5</u> % to <u>8.5</u> %	TEMPERATURES - AIR - SLUMP Intended Slump <u>0</u> " to <u>3/6</u> "

TIME	ATMOSPHERE	CONCRETE	*AIR CONTENT %	SLUMP	CYLINDERS/ BEAMS	TIME	ATMOSPHERE	CONCRETE	*AIR CONTENTS %	SLUMP	CYLINDERS/ BEAMS
① 7:10am	63°F	81°F	5.9%	2"	4						
② 10:50am	76°F	85°F	6.2%	4.25"	4						

LOT #	LOT SIZE	SUBLOT #	SUBLOT SIZE	RANDOM #	QA Cylinder ID	Discrepancy Cylinder

COMMENTS *poured by truck chute

ITEM OR CODE NO.	STA. TO STA.	GRADE OF CONC.	LENGTH	WIDTH	DEPTH	MEASURED SQ. OR CU. YARDS	CYDS. PLAN	CYDS. USED	CYDS. WASTE	OVER UNDER %

REMARKS OR COMPUTATIONS (Use back if necessary)	① ticket 2514279 PISSE7CRA032 24 cyd	② ticket 2514464 PISSE7CRA032 11 cyd
MIX OR STREET TECHNICIAN	DATE <u>7/24/20</u>	
<u>Mallory Grager</u> <u>Mallory Grager</u>		

