

Michigan Department
Of Transportation
1174R (08/12)

INSPECTOR'S REPORT OF CONCRETE PLACED - Roadway

CONTRACTOR <u>Merlo Construction</u>		GENERAL NAME OF PROJECT <u>MDOT-Various Detroit</u>	
SUBCONTRACTOR		CONTROL SECTION ID - JOB NUMBER	
CONCRETE SUPPLIER <u>Superior Materials</u>		ROUTE <u>Joseph Campau St.</u>	
MAXIMUM TIME <u>90 minutes</u>		STRUCTURE NUMBER	
WEATHER <u>partly cloudy</u> A.M. <u>partly cloudy</u> P.M.		REPORT NUMBER	
MAX. WATER ADDED PER CYD GALLONS		DATE <u>7/28/20</u>	
REASON:		CURING COMPND. USED GALLONS	
BEAMS/CYLINDERS MADE (Sta, Time, #, etc.) <u>NE ADA ramps/sidewalk at Joseph Campau St & Grant St</u>			

Intended Air 5.5 % to 8.5 % TEMPERATURES - AIR - SLUMP Intended Slump 0 " to 3 "

TIME	ATMOSPHERE	CONCRETE	*AIR CONTENT %	SLUMP	CYLINDERS/ BEAMS	TIME	ATMOSPHERE	CONCRETE	*AIR CONTENTS %	SLUMP	CYLINDERS/ BEAMS
12:40pm	84°F	79°F	6.2%	2.5"	4						

LOT #	LOT SIZE	SUBLOT #	SUBLOT SIZE	RANDOM #	QA Cylinder ID	Discrepancy Cylinder

COMMENTS *poured by truck chute
*NO QA present

ITEM OR CODE NO.	STA. TO STA.	GRADE OF CONC.	LENGTH	WIDTH	DEPTH	MEASURED SQ. OR CU. YARDS	CYDS. PLAN	CYDS. USED	CYDS. WASTE	OVER UNDER %

REMARKS OR COMPUTATIONS
(Use back if necessary)

ticket 2515907
P155E/CQAD32
20 yd

MIX OR STREET TECHNICIAN

Mallory Graeger Mary Gage

DATE 7/28/20