

INSPECTOR'S REPORT OF CONCRETE PLACED - Roadway

FILE 210

CONTRACTOR		GENERAL NAME OF PROJECT VARIOUS PROJECTS	
SUBCONTRACTOR MERLO CONSTRUCTION		CONTROL SECTION ID - JOB NUMBER E1B BAGLEY	
CONCRETE SUPPLIER SUPERIOR MATERIALS		ROUTE BETWEEN - TRUMBULL + 24TH ST	
MAXIMUM TIME 90 MIN		STRUCTURE NUMBER CURB + SIDEWALK + ADA	
WEATHER CLDY 56 A.M. CLDY 68 P.M.		REPORT NUMBER 1829	DATE 9-16-20
MAX. WATER ADDED PER CYD GALLONS		REASON:	
BEAMS/CYLINDERS MADE (Sta, Time, #, etc.)			CURING COMPND. USED GALLONS

TEMPERATURES - AIR - SLUMP						Intended Slump 10" to 5"					
Intended Air 55% to 8.5%											
TIME	ATMOSPHERE	CONCRETE	*AIR CONTENT %	SLUMP	CYLINDERS/BEAMS	TIME	ATMOSPHERE	CONCRETE	*AIR CONTENT %	SLUMP	CYLINDERS/BEAMS
① 8:00	57	71	7.3	4.5	4						
② 11:15	67	73	6.8	4.75	—						
③ 3:25	75	81	8.2	9.5	4						
④					4						

LOT #	LOT SIZE	SUBLOT #	SUBLOT SIZE	RANDOM #	QA Cylinder ID	Discrepancy Cylinder
①	TICKET - 2533675		SIDEWALK + ADA		SW CORNER	BAGLEY + VERMONT
②	TICKET - 2533874		SIDEWALK + E1B		BAGLEY + WABASH	
③	TICKET - 2534120		SIDEWALK + ADA		E1A - BAGLEY + ST ANNE	

COMMENTS **SAMPLE FROM TRUCK CHUTE**

ITEM OR CODE NO.	STA. TO STA.	GRADE OF CONC.	LENGTH	WIDTH	DEPTH	MEASURED SQ. OR CU. YARDS	CYDS. PLAN	CYDS. USED	CYDS. WASTE	OVER UNDER %

REMARKS OR COMPUTATIONS (Use back if necessary) **78 - TOTAL YDS**

MIX OR STREET TECHNICIAN

① PISSERCQA032

DATE **9-16-20**

