



CONSTRUCTION CONSULTING & TESTING, INC.

TOLEDO OFFICE - 700 S. River Rd. Waterville, Ohio 43566 Ph.: (419) 878-7304
DETROIT OFFICE - 35410 Mound Rd. Sterling Hts., Michigan 48310 Ph.: (586) 795-2877

Client: Merlo Construction Co., Inc.
4964 Technical Dr.
Milford, MI 48381

Project: PW 7023
Merlo: 22-151

Date: November 30, 2022

CCT No.: 201-22099-1

Page: 1 of 2

REPORT OF SERVICES

As requested, a representative of CCT reported to the above referenced project to perform concrete QA/QC Testing. Results are attached.

<u>Mix ID</u>	<u>Item Description</u>	<u>Concrete Placed</u>	<u>Plan Quantity</u>
P1-DET	Curb	10.0 yd ³	

Technician J. Richardson	Project Time 9:00 AM - 1:00 PM	Mileage
-----------------------------	-----------------------------------	---------

Field Notes:

Attachments: Concrete Field Report

Distribution: Brian Gustin - Merlo

CONCRETE FIELD QA/QC INSPECTION REPORT

Project: PW 7023				Mix Type: P1			Theo. Unit Weight:			Air Spec.: 5.5" to 8" Max		
Contractor: Merlo				Mix ID: P1-DET			Theo. Yield:			Slump Spec.: 3" Max		
Consultant: CCT				Lot No.:			Supplier: Hercules			Temp. Spce.: 50-90°		
Tester: J. Richardson				Lot Size:			Plant: Centerline			Time Spec.: 60 Max		
Signature:				Date: November 30, 2022								

Test No.	Ticket No.	Yds./Cum.	No. of Cylinders	Batch Time	Empty Time	Air Content	Slump	Concrete Temp	Air Temp.	Unit Weight	Yield
QC-1	452911	10/10	4	11:18 AM	12:35 PM	6.4	3	58	34	---	---

General Location: Curb

Test No.	Cylinder ID	Location:
QC-1	Set 1	NW corner Warren & Conner

Total Placed:	10.0 yd ³
---------------	----------------------

Comments: _____

Construction Consulting & Testing, Inc. P. O. Box 287 Waterville, Ohio 43566
Ph: 419-878-7304 Fax: 419-878-7305

Client: Merlo Construction Co., Inc.
4964 Technical Dr.
Milford, MI 48381

Date: 11/30/2022
CCT No.: 201-22099-1
Page: 2 of 2