

REQUEST FOR INFORMATION

RFI # 009

Page 1 of 2

GENERAL INFORMATION	
RFI SUBJECT Drainage	CONTROL SECTION
JOB DESCRIPTION PW 7017 Puritan	JOB NUMBER PW 7017
CONTRACTOR Major Cement Co.	
LOCATION Purtian	DATE 04/26/21
INFORMATION REQUEST	

Existing conditions and grade on Puritan are creating an area that's holding water and debris.

Per our site review, replacing curb and providing a new drainage structure cover before asphalt paving may improve drainage.

Please review and provide direction as appropriate. Thanks...

See revised grading for this area on the attached C501 sheet.

CITY OF DETROIT RESPONSE

Approved by (CED Representative):

Alan C. Fo 5-12-2021



REVISIONS	
NO.	DATE
1	10/1/01
2	10/1/01
3	10/1/01
4	10/1/01
5	10/1/01
6	10/1/01
7	10/1/01
8	10/1/01
9	10/1/01
10	10/1/01

Crane fly	0.27
Scorpion	0.27
Housefly	0.27
Spider	0.27

Hard copy is intended to be 24"x36" when plotted. Scale(s) indicated and graphic quality may not be accurate for any other size.

104105

Sheet No.

C501

100

BENCH MARKS

ORIENTAL DRUM NA0033
 THERMAL DATA NA0088

 BENCH MARK A
 NORTHWEST SQUARE ON NORTHEAST SIDE OF
 CONCRETE LIGHT POLE
 WEST QUARTER OF GRAND RIVER AVENUE AND
 CLEVELAND AVENUE
 ELEVATION 832.28
 1329231.33
 1342853.70

 BENCH MARK B
 SAG SPIKE ON NORTH SIDE OF UTILITY POLE AT THE
 SOUTHWEST CORNER OF GREENBROOK AND
 EUGENE RD
 ELEVATION 832.86
 1342853.86
 1342873.95

SPOT ELEVATION LEGEND

[illegible]

VOTE

ALL CONSTRUCTION SHALL CONFORM TO THE CURRENT STANDARDS AND SPECIFICATIONS OF THE CITY OF DETROIT.

