



**DRIESENKA &
ASSOCIATES, INC.**

Engineering • Surveying • Testing

CONCRETE FIELD TEST REPORT

CLIENT: <u>Westside Concrete</u>	D&A PROJECT NO.: <u>2020525.4A</u>	DATE: <u>7-10-2020</u>
PROJECT: <u>Detroit PU-7018</u>	INSPECTOR: <u>Patrick Drumm</u>	
CONTRACTOR: <u>Westside Concrete</u>	CONTROL SECTION/MDOT JOB NO.:	
CONCRETE SUPPLIER & CITY: <u>McGraw</u>	PROJECT ENGINEER: <u>City of Detroit</u>	
WEATHER: <u>Sunny</u>	TIME ARRIVED:	
A.M. <u>85</u>	SCHEDULED ARRIVAL TIME:	
P.M.	TIME LEFT SITE:	
AGGREGATE CORRECTION FACTOR: <u>0.2</u>		

Pour Description: Sealed & 7 Mile - Various Details

Mix Design: P1-SM Quantity Placed (yd³): 11 Lot Number: _____ Sublot: _____
Grade of Concrete: P1 Batch Quantity (yd³): 11 Pour Start: _____ Pour End: _____

FIELD TEST RESULTS

Truck No.	Ticket #	Batch Time	Start	Empty	Slump (in)	Air Temp. (°F)	Conc. Temp. (°F)	Air Content (%)	Unit Wt. (pcf)	Yield	No. of Cylinders
4526	11138169	7:47		9.15	4.72	85	88	5.8			4 DCI

REMARKS

W/ DAE - BA & CMRLI-PR