



**DRIESEN &
ASSOCIATES, INC.**

Engineering • Surveying • Testing

CONCRETE FIELD TEST REPORT

CLIENT: <u>West Side Concrete</u>
PROJECT: <u>Detroit PM 7018</u>
CONTRACTOR: <u>West Side Concrete</u>
CONCRETE SUPPLIER & CITY: <u>Mecoig materials, Warren</u>
WEATHER: A.M. <u>Sunny</u> P.M.
AGGREGATE CORRECTION FACTOR: <u>0.2</u>

D&A PROJECT NO.: <u>2020525.4A</u>	DATE: <u>07-14-20</u>
INSPECTOR: <u>M. Bouque</u>	
CONTROL SECTION/MDOT JOB NO.:	
PROJECT ENGINEER: <u>City of Detroit</u>	
TIME ARRIVED: <u>8:30</u> SCHEDULED ARRIVAL TIME: <u>8:30</u> TIME LEFT SITE: <u>11:00AM</u>	

Pour Description: North-West corner of Sherwood and Nevada
St E.

Mix Design: P1-SM Quantity Placed (yd³): 33.0 Lot Number: — Sublot: —

Grade of Concrete: P1 Batch Quantity (yd³): 33.0 Pour Start: 9:20 Pour End: —

FIELD TEST RESULTS

Truck No.	Ticket #	Batch Time	Start	Empty	Slump (in)	Air Temp. (°F)	Conc. Temp. (°F)	Air Content (%)	Unit Wt. (pcf)	Yield	No. of Cylinders
4902	14138319	8:32	9:20	9:50	5 3/4	75	81	6.8	142.4	1.005	4 DCI

REMARKS

