



**DRIESEN &
ASSOCIATES, INC.**

Engineering • Surveying • Testing

CONCRETE FIELD TEST REPORT

CLIENT: <u>Westside Concrete</u>	D&A PROJECT NO.: <u>2020S25.4A</u>	DATE: <u>7-21-2020</u>
PROJECT: <u>Detroit PW - 7018</u>	INSPECTOR: <u>Patrick Drumm</u>	
CONTRACTOR: <u>Westside Concrete</u>	CONTROL SECTION/MDOT JOB NO.:	
CONCRETE SUPPLIER & CITY: <u>Morris - Detroit</u>	PROJECT ENGINEER:	
WEATHER: <u>clear</u> A.M. <u>70</u> P.M.	TIME ARRIVED: <u>7:30</u> SCHEDULED ARRIVAL TIME: <u>7:30</u> TIME LEFT SITE:	
AGGREGATE CORRECTION FACTOR: <u>0.2</u>		

Pour Description: Sidewalk - Various locations in front of Detroit Northwestern HS - S Side of W Grand B/V

Mix Design: P1-015" Quantity Placed (yd³): 1 Lot Number: _____ Sublot: _____
Grade of Concrete: P1 Batch Quantity (yd³): 33.01 Pour Start: _____ Pour End: _____

FIELD TEST RESULTS

Truck No.	Ticket #	Batch Time	Start	Empty	Slump (in)	Air Temp. (°F)	Conc. Temp. (°F)	Air Content (%)	Unit Wt. (pcf)	Yield	No. of Cylinders
3711	2504001	7-28	8:10	8:45	4 3/4	70	83	6.6	112.6	0.958	4 Cyl

REMARKS