



**DRIESEN &
ASSOCIATES, INC.**

Engineering • Surveying • Testing

CONCRETE FIELD TEST REPORT

CLIENT: <u>Westside Concrete</u>
PROJECT: <u>Detroit PW-7018</u>
CONTRACTOR: <u>Westside Concrete</u>
CONCRETE SUPPLIER & CITY: <u>McCoy - Springwell, Detroit</u>
WEATHER: A.M. <u>72° Cloudy</u> P.M.
AGGREGATE CORRECTION FACTOR: <u>1.2</u>

D&A PROJECT NO.: <u>2020525-4A</u>	DATE: <u>7-22-20</u>
INSPECTOR: <u>Jackie Richards</u>	# <u>01362857</u>
CONTROL SECTION/MDOT JOB NO.: <u>—</u>	
PROJECT ENGINEER:	
TIME ARRIVED: <u>7:50</u> SCHEDULED ARRIVAL TIME: <u>8:00</u> TIME LEFT SITE: <u>9:20</u>	

Pour Description: Side walks on W. Grand Blvd
going Eastbound - btwn Grandriver & Linwood Ave

Mix Design: P1-DETH Quantity Placed (yd³): 11.0 Lot Number: — Sublot: —

Grade of Concrete: P1 Batch Quantity (yd³): 11.0 Pour Start: 8:30 Pour End: 9:20

FIELD TEST RESULTS

Truck No.	Ticket #	Batch Time	Start	Empty	Slump (in)	Air Temp. (°F)	Conc. Temp. (°F)	Air Content (%)	Unit Wt. (pcf)	Yield	No. of Cylinders
56 3726	2204097	7:31	8:30	9:20	4 1/2"	72°	83°	6.2	139.6	1.019	001-4

REMARKS