



DRIESEN & ASSOCIATES, INC.

Engineering • Surveying • Testing

CONCRETE FIELD TEST REPORT

CLIENT: <u>Westside Concrete</u>	D&A PROJECT NO.: <u>1020525.4A</u>	DATE: <u>7-23-2020</u>
PROJECT: <u>Detroit PW-7018</u>	INSPECTOR: <u>Zach Brown</u>	
CONTRACTOR: <u>Westside Concrete</u>	CONTROL SECTION/MDOT JOB NO.:	
CONCRETE SUPPLIER & CITY: <u>McCOIK Materials, Warren</u>	PROJECT ENGINEER: <u>City of Detroit</u>	
WEATHER: A.M. P.M. <u>Cloudy / 50°</u>	TIME ARRIVED: <u>1:30 PM</u> SCHEDULED ARRIVAL TIME: <u>1:30</u> TIME LEFT SITE: <u>4:00</u>	
AGGREGATE CORRECTION FACTOR: <u>.2</u>		

Pour Description: Curb and gutter / G. down along Sherwood St. at intersections, Sherwood St and E Robbwood St / Sherwood St and Elywood St.

Mix Design: M-DET Quantity Placed (yd³): _____ Lot Number: 1 Sublot: _____

Grade of Concrete: P1 Batch Quantity (yd³): 80 yds Pour Start: 2:25 Pour End: N/A

FIELD TEST RESULTS

Truck No.	Ticket #	Batch Time	Start	Empty	Slump (in)	Air Temp. (°F)	Conc. Temp. (°F)	Air Content (%)	Unit Wt. (pcf)	Yield	No. of Cylinders
4808	14138816	1:25	2:25	2:40	3 1/2	79	88	5.9	147.250	989	2 (1 core)

REMARKS

- Mix contains MC - Informed Westside of retesting
★ NO QA truck due to time limit, but pour continues