



**DRIESEN &
ASSOCIATES, INC.**

Engineering • Surveying • Testing

CONCRETE FIELD TEST REPORT

CLIENT: <i>Westside Concrete</i>	D&A PROJECT NO.: <i>2020S2S.4A</i>	DATE: <i>7-28-20</i>
PROJECT: <i>Detroit PW-7018</i>	INSPECTOR: <i>Joe Kennedy 01266483</i>	
CONTRACTOR: <i>Westside Concrete</i>	CONTROL SECTION/MDOT JOB NO.: <i>PW-7018</i>	
CONCRETE SUPPLIER & CITY: <i>Mixco - Detroit</i>	PROJECT ENGINEER:	
WEATHER: A.M. <i>partly cloudy 85°</i> P.M.	TIME ARRIVED: SCHEDULED ARRIVAL TIME: TIME LEFT SITE: <i>12:20pm</i>	
AGGREGATE CORRECTION FACTOR:		

Pour Description: *Various Subgrade Locations on West Forest Ave.*

Mix Design: *P1-SM-b2* Quantity Placed (yd³): _____ Lot Number: _____ Sublot: _____

Grade of Concrete: *P1* Batch Quantity (yd³): *33* Pour Start: _____ Pour End: _____

FIELD TEST RESULTS

Truck No.	Ticket #	Batch Time	Start	Empty	Slump (in)	Air Temp. (°F)	Conc. Temp. (°F)	Air Content (%)	Unit Wt. (pcf)	Yield	No. of Cylinders
<i>4820</i>	<i>2204480</i>	<i>10:35</i>	<i>11:00</i>		<i>9 1/2</i>	<i>83</i>	<i>84</i>	<i>6.5</i>			<i>4cc</i>

REMARKS

M. & contains M.P.W.