



**DRIESEN &
ASSOCIATES, INC.**

Engineering • Surveying • Testing

CONCRETE FIELD TEST REPORT

CLIENT: <i>Westside Concrete</i>
PROJECT: <i>Detroit PW-7018</i>
CONTRACTOR: <i>Westside Concrete</i>
CONCRETE SUPPLIER & CITY: <i>McCaig-Detroit</i>
WEATHER: A.M. <i>Sunny</i> P.M.
AGGREGATE CORRECTION FACTOR: <i>2%</i>

D&A PROJECT NO.: <i>20200254A</i>	DATE: <i>7-31-20</i>
INSPECTOR: <i>Joe Kennedy 01268923</i>	
CONTROL SECTION/MDOT JOB NO.: <i>PW-7018</i>	
PROJECT ENGINEER:	
TIME ARRIVED: <i>9:00 am</i> SCHEDULED ARRIVAL TIME: <i>1:00 am</i> TIME LEFT SITE: <i>10:00 am</i>	

Pour Description: *VARIOUS curb & sidewalk locations on corridor for it*

Mix Design: *P1-SW* Quantity Placed (yd³): _____ Lot Number: _____ Sublot: _____
Grade of Concrete: *P1* Batch Quantity (yd³): _____ Pour Start: *9:50* Pour End: _____

FIELD TEST RESULTS

Truck No.	Ticket #	Batch Time	Start	Empty	Slump (in)	Air Temp. (°F)	Conc. Temp. (°F)	Air Content (%)	Unit Wt. (pcf)	Yield	No. of Cylinders
<i>46121231811</i>		<i>9:16</i>	<i>9:50</i>		<i>2</i>		<i>81</i>	<i>7.0</i>			<i>400</i>

REMARKS

