



**DRIESENKA &
ASSOCIATES, INC.**

Engineering • Surveying • Testing

CONCRETE FIELD TEST REPORT

CLIENT: <u>Westside Concrete</u> <u>P</u>	D&A PROJECT NO.: <u>2020525.4A</u>	DATE: <u>8-10-2020</u>
PROJECT: <u>Detroit PW-7018</u>	INSPECTOR: <u>Patrick Drumm</u>	
CONTRACTOR: <u>Westside Concrete</u>	CONTROL SECTION/MDOT JOB NO.:	
CONCRETE SUPPLIER & CITY: <u>Mixing - Detroit</u>	PROJECT ENGINEER: <u>City of Detroit</u>	
WEATHER: <u>Sunny</u> A.M. <u>82°F</u> P.M.	TIME ARRIVED: <u>10:30</u> SCHEDULED ARRIVAL TIME: <u>10:30</u> TIME LEFT SITE:	
AGGREGATE CORRECTION FACTOR: <u>0.2</u>		

Pour Description: Sidewalk - From Greenbelt Ave to Rosemont Ave - S side of Tremain St

Mix Design: P1 DETM Quantity Placed (yd³): _____ Lot Number: _____ Sublot: _____
Grade of Concrete: P1 Batch Quantity (yd³): 33 Pour Start: 11:00 Pour End: _____

FIELD TEST RESULTS

Truck No.	Ticket #	Batch Time	Start	Empty	Slump (in)	Air Temp. (°F)	Conc. Temp. (°F)	Air Content (%)	Unit Wt. (pcf)	Yield	No. of Cylinders
4831	1232551	10:35	11:00		4	82	88	7.6	1416	1.008	4 QCI

REMARKS

W/OMRLI-PR, DAT-CA