



DRIESENKA & ASSOCIATES, INC.

Engineering • Surveying • Testing

CONCRETE FIELD TEST REPORT

CLIENT: <u>Westside Concrete</u>	D&A PROJECT NO.: <u>2020525.4A</u>	DATE: <u>8-20-2020</u>
PROJECT: <u>Detroit PW - 7018</u>	INSPECTOR: <u>Patrick Drumm</u>	
CONTRACTOR: <u>Westside Concrete</u>	CONTROL SECTION/MDOT JOB NO.:	
CONCRETE SUPPLIER & CITY: <u>Melroe - Detroit</u>	PROJECT ENGINEER: <u>City of Detroit</u>	
WEATHER: <u>Sunny</u> A.M. <u>73</u> P.M.	TIME ARRIVED: SCHEDULED ARRIVAL TIME: TIME LEFT SITE:	
AGGREGATE CORRECTION FACTOR: <u>0.2</u>		

Pour Description: Subgrade - Various locations W Side of Wyandotte St from Chippewa St to

Mix Design: P1-SM Quantity Placed (yd³): 11 Lot Number: Sublot: 11
Grade of Concrete: P1 Batch Quantity (yd³): 33 Pour Start: 10:30 Pour End:

FIELD TEST RESULTS

Truck No.	Ticket #	Batch Time	Start	Empty	Slump (in)	Air Temp. (°F)	Conc. Temp. (°F)	Air Content (%)	Unit Wt. (pcf)	Yield	No. of Cylinders
2446	1233265	9:46	10:30		4 1/2	73	78	7.4	135.2	1.065	2

REMARKS

W/ ONE BA, W/ 1.065