



**DRIESEN &
ASSOCIATES, INC.**

Engineering • Surveying • Testing

CONCRETE FIELD TEST REPORT

CLIENT: <u>Upside Concrete</u>	D&A PROJECT NO.: <u>2020525.4A</u>	DATE: <u>11-3-2020</u>
PROJECT: <u>Detroit PI-7B</u>	INSPECTOR: <u>Patrick Drumm</u>	
CONTRACTOR: <u>Upside Concrete</u>	CONTROL SECTION/MDOT JOB NO.:	
CONCRETE SUPPLIER & CITY: <u>McGregor - Detroit</u>	PROJECT ENGINEER: <u>City of Detroit</u>	
WEATHER: <u>Clear</u> A.M. P.M.	TIME ARRIVED: SCHEDULED ARRIVAL TIME: TIME LEFT SITE:	
AGGREGATE CORRECTION FACTOR: <u>0.2</u>		

Pour Description: Curb & Sidewalk at 91st St & Trieman St

Mix Design: PI-SW Quantity Placed (yd³): _____ Lot Number: _____ Sublot: _____
Grade of Concrete: P1 Batch Quantity (yd³): 33 Pour Start: 9:10 Pour End: _____

FIELD TEST RESULTS

Truck No.	Ticket #	Batch Time	Start	Empty	Slump (in)	Air Temp. (°F)	Conc. Temp. (°F)	Air Content (%)	Unit Wt. (pcf)	Yield	No. of Cylinders
6634	124243	8:31	9:10	9:31	3	63.45	63	5.7	141.2	1.006	4 ACI

REMARKS