



**DRIESENGA &
ASSOCIATES, INC.**

Engineering • Surveying • Testing

CONCRETE FIELD TEST REPORT

CLIENT: <u>West Side Concrete Co.</u>	D&A PROJECT NO.: <u>2020525-4A</u>	DATE: <u>11-6-2020</u>
PROJECT: <u>PW-7018 CITY OF Detroit</u>	INSPECTOR: <u>Mekehon P. Boarive</u>	
CONTRACTOR: <u>West Side Concrete Co.</u>	CONTROL SECTION/MDOT JOB NO.:	
CONCRETE SUPPLIER & CITY: <u>McCloy Materials, Detroit</u>	PROJECT ENGINEER: <u>CITY OF DETROIT</u>	
WEATHER: A.M. <u>Sunny</u> P.M.	TIME ARRIVED: <u>8:20</u> SCHEDULED ARRIVAL TIME: <u>9:00</u> TIME LEFT SITE: <u>11:05</u>	
AGGREGATE CORRECTION FACTOR: <u>0.20</u>		

Pour Description: Curband Side walk South-west and South-east corner of Tireman St / Warwick St

Mix Design: PL-SW Quantity Placed (yd³): 33.01 Lot Number: — Sublot: —

Grade of Concrete: PL Batch Quantity (yd³): 33.01 Pour Start: 9:25 Pour End: 10:45

FIELD TEST RESULTS

Truck No.	Ticket #	Batch Time	Start	Empty	Slump (in)	Air Temp. (°F)	Conc. Temp. (°F)	Air Content (%)	Unit Wt. (pcf)	Yield	No. of Cylinders
2352	1240350	8:29	9:25	11:10	3 1/4	52	67	7.0	1420	1.012	4 Cyl

REMARKS
