



**DRIESEN &
ASSOCIATES, INC.**

Engineering • Surveying • Testing

CONCRETE FIELD TEST REPORT

CLIENT: <u>Westside</u>	D&A PROJECT NO.: <u>2020525.4A</u>	DATE: <u>11-9-2020</u>
PROJECT: <u>Detroit PW 7018</u>	INSPECTOR: <u>Jon Morris 01293676</u>	
CONTRACTOR: <u>Westside</u>	CONTROL SECTION/MDOT JOB NO.: <u>Detroit 7018</u>	
CONCRETE SUPPLIER & CITY: <u>SEM concrete - 1 mile</u>	PROJECT ENGINEER: <u>City of Detroit</u>	
WEATHER: A.M. <u>Sunny</u> P.M. <u>—</u>	TIME ARRIVED: <u>8:30 AM</u> SCHEDULED ARRIVAL TIME: <u>8:30 AM</u> TIME LEFT SITE: <u>10:15 AM</u>	
AGGREGATE CORRECTION FACTOR: <u>.2</u>		

Pour Description: curb + gutter + curb radius + sidewalk on Tireman Ave multiple locations From Ashion Ave to Evergreen Rd

Mix Design: pl-sw Quantity Placed (yd³): 33 Lot Number: _____ Sublot: _____

Grade of Concrete: pl Batch Quantity (yd³): 33 Pour Start: 9:15 AM Pour End: 10:30 AM

FIELD TEST RESULTS

Truck No.	Ticket #	Batch Time	Start	Empty	Slump (in)	Air Temp. (°F)	Conc. Temp. (°F)	Air Content (%)	Unit Wt. (pcf)	Yield	No. of Cylinders
2135	817103	8.19	9.15	9.35	22	57	66	5.5	143.6	1.004	4QCI

REMARKS

Mix pl-sw contained OAE-BA and OWPA-DR