



DRIESENKA & ASSOCIATES, INC.

Engineering • Surveying • Testing

CONCRETE FIELD TEST REPORT

CLIENT: <i>Westside Concrete</i>	D&A PROJECT NO.: <i>2020525.4A</i>	DATE: <i>11-19-20</i>
PROJECT: <i>detroit - pw</i>	INSPECTOR: <i>Sae Kennedy 01268983</i>	
CONTRACTOR: <i>Westside Concrete</i>	CONTROL SECTION/MDOT JOB NO.: <i>PW-7018</i>	
CONCRETE SUPPLIER & CITY: <i>SRM Concrete Detroit</i>	PROJECT ENGINEER:	
WEATHER: A.M. <i>Sunny/51°</i> P.M.	TIME ARRIVED: <i>8:30am</i> SCHEDULED ARRIVAL TIME: <i>8:30am</i> TIME LEFT SITE: <i>10:30am</i>	
AGGREGATE CORRECTION FACTOR: <i>1.2%</i>		

Pour Description: *Various curb & sidewalk locations on Forest Ave*

Mix Design: *P1-detroit* Quantity Placed (yd³): _____ Lot Number: _____ Sublot: _____

Grade of Concrete: *P1* Batch Quantity (yd³): _____ Pour Start: *9:50am* Pour End: _____

FIELD TEST RESULTS

Truck No.	Ticket #	Batch Time	Start	Empty	Slump (in)	Air Temp. (°F)	Conc. Temp. (°F)	Air Content (%)	Unit Wt. (pcf)	Yield	No. of Cylinders
2403	617908	9:23	9:50		4	51	64	6.0	143.1	1.001	400

REMARKS

Mix contains air